




## Vexve Smart Valve Solution Vexve智能阀门解决方案

16.-18.5.2017 Sino-Finnish Energy Days  
2017年5月16-18日 Sino-Finnish 能源日

Jussi Vanhanen, CEO  
万年希, 首席执行官


# Reliable over generations. Today Safe, Smart & Sustainable

今天，安全、智能、可持续产品的选择。未来，可依赖的长久服务与支持的伙伴。



# INDUSTRY - Transition from 4th to 5th generation network

产业-由第4代到第5代网络的转变



Remote Control: Reliable – easy to use – cost effective

远程控制: 可信- 使用方便- 高性价比





**VEXVE**

No: 188050  
T max: 140  
DN 50 / P



- Traceability of the supply chain  
供应链具有可追溯性
- Valve technical information  
阀门技术资料
- Installation information  
安装信息

elisa vexve.com

**VEXVE OY**

Vexve.com / Solutions /

## Heating, Ventilation, Air Conditioning/Refrigeration (HVAC/R)

Vexve Oy is a leading manufacturer of high quality, fully-welded ball valves for opening and closing (shut off) heating and cooling pipelines.

Vexve balancing valves, utilized for balancing heating and cooling systems, are designed for maximum energy efficiency as well as easy installation and



# Service database

**Equipment details**

725130 Steel Ball Valve, GOST, DN 700 **ACTIVE**  
Serial: #641002911.10009298  
9 Fortum, Turuntie 154, Turku  
Vexve, Pajakatu 11, Sastamala

**Specifications:**

Max. torque:	15.650 Nm
Operating conditions:	-30 °C - +200 °C

**Usage data:**

Deployment date:	02.01.2014
Last service:	19.08.2015
Last maintenance:	04.01.2016 <b>OK</b>

**Transactions**

Last Maintenance	Next Maintenance (scheduled)	Maintenance (days)
04.01.2016	04.07.2016	

- John Simpson** (Maintenance) posted a test result 7 days ago  
Scheduled engine maintenance - OK
- Sari Vaara** (Fortum) posted a goods receipt 1 year 5 months ago  
Return from a service.
- John Simpson** (Maintenance) carried out a repair & calibration 1 year 5 months ago  
Engine repaired. Calibration OK.
- Marja Marjanen** (Maintenance) posted goods receipt for service 1 year 5 months ago  
Delivery document: 80001248
- Sari Vaara** (Fortum) made a service request 1 year 5 months ago  
Requesting: Repair & Calibration. Description: Engine stuck.

**Actions and Docs**

- Service Request
- Activate/deactivate
- Product data sheet

→ *Online / Offline Data Collector*  
在线/离线数据收集器

- ❑ Service information  
服务信息
- ❑ Service log  
服务日志
- ❑ Predictive maintenance support  
预见性维护支持



Together we are  
Closing lines – Opening options